

MADERA UNIFIED SCHOOL DISTRICT 1902 Howard Road Madera CA 93637 (559) 675-4500 (559) 675-1186 Fax www.madera.k12.ca.us

Board of Trustees: <u>President</u>: Al Galvez

<u>Clerk</u>: Ed McIntyre

<u>Trustees</u>: Ricardo Arredondo Brent Fernandes Philip Huerta Ruben Mendoza Ray G. Seibert

SUPERINTENDENT: Todd Lile

March 6, 2018

Addendum No. 1 Bid No.020118-Exterior Painting at Various School Sites

NOTICE TO ALL VENDORS:

This Addendum is attached to and made a part of the above entitled specifications for Madera Unified School District for Bid No.020118 with a due date of March 13, 2018.

All changes and/or clarifications will appear in bold type and deletions will be struck out within a sentence.

Questions/Clarifications: Bid Section No.2, **3**-Sierra Vista Bid Section No. 3,**4**-Adams

Bid Bonds-You can either submit one Bid Bond for the Total off all the sections you are bidding on or you can submit a Bid Bond Per Bid Section.

Please refer to the Bid Documents for the Bid Section Turn in Times. You must submit a Bid Packet per bid section per the instructions on the Notice to Bidders.

All Projects-No re-striping of Parking Lots and Game Courts No lead testing required-District will take ownership if needed Dry Rot-District will handle replacing any dry rot. Pressure Wash entire site prior to painting

Bid Section No.1-Nishimoto: Interior fence to be painted-do not paint the perimeter fence Do no paint the roof or structures on the roof "C" trains to be painted Shed by pre-school to be painted Exterior on Windows Complete prime on body and two (2) finish cotes <u>Bid Section No.2-Pershing:</u> Wrought Iron to be painted black DO NOT paint cyclone fence by preschool All handrails to be painted Complete prime on body and two (2) finish coats Yes-Paint preschool and shed by preschool

Bid Section No.3-Sierra Vista: Refer to the map in the Bid Documents that is posted on the website for the buildings to be painted. "C" trains are to be painted Remove and reinstall window screens Brick-Pressure wash only All raw wood to be primed prior to painting Conduit to be primed and painted T111-MUSD will handle dry rot Door Sweeps-are to be painted End Caps on rails to be painted "Safety Yellow" No paint for white vinyl windows DO NOT PAINT MURALS Doors to be painted interior/exterior and Wraparound Spot prime where needed/two (2) finish cotes

Bid Section No.4-Adams: Remove and reinstall screens Door sweeps are to be painted Wood Ramps to be painted and non-skid applied Do not paint aluminum surfaces End caps on rails to be painted "Safety Yellow" Raw wood to be primed and painted All brick to be pressured washed-only Spot prime where needed/two (2) finish cotes

Signature:_____

Date:_____