



**MADERA UNIFIED
SCHOOL DISTRICT**
1902 Howard Road
Madera CA 93637
(559) 675-4500
(559) 675-1186 Fax
www.madera.k12.ca.us

Board of Trustees:

President:
Ed McIntyre

Clerk:
Lucy Salazar

Trustees:
Nadeem Ahmad
Isreal Cortez
Joetta Fleck
Ruben Mendoza
Lucy Salazar
Ray G. Seibert

SUPERINTENDENT:
Todd Lile

February 1, 2022

**Addendum No.2 Bid No.010522-Thomas Jefferson MS HVAC
Project**

NOTICE TO ALL VENDORS:

This Addendum is attached to and made a part of the above-entitled specifications for Madera Unified School District for **Bid No. 010522-Thomas Jefferson MS HVAC Project** with a due date of February 9, 2022 @ 10:01 am

All changes and/or clarifications will appear in bold type and deletions will be struck out within a sentence.

Questions/Clarifications:

Updated Bid Turn In-Due date of February 9, 2022 @ 10:01 am.

Responses to RFI" s

DRAWINGS:

Item 2-01 – Sheet M0.2:

Air Distribution Schedule: Symbol G shall be changed to the following: Fixed louvered face diffuser, aluminum construction. Titus model TDC-1.

Item 2-02 – Sheet M2.1: A. Symbol G diffusers shall be changed to 48"x12"-4 size and the 36"x9" duct drops thru roof in keynote 4 shall be revised to 48"x9" with transition at ceiling grille.

Pre-Bid Questions and Clarifications

- 1. Is the existing gym floor concrete or wood framing?**
Response: Concrete
- 2. Is there a specific method for gym floor protection required?**
Response: No, the contractor controls its means and methods
- 3. Have the ceiling tiles and glue in the wrestling room been tested for asbestos?**
Response: No. The District will have them surveyed. The District will be responsible for abatement if asbestos is found.
- 4. What is the ceiling finish material in the gym?**
Response: The ceiling appears to be acoustic gyp board.

February 1, 2022

Addendum No.2 Bid No.010522-Thomas Jefferson MS HVAC Project (cont.)

- 5. The roofing detail (Sheet E3.2 / Detail 2) illustrates laying the B-22 channel directly on the roofing. On the job walk, I noticed that the existing conditions were utilizing roof blocks. Please advise.**

Response: The use of Cooper B-Line DB Series roof supports is acceptable for intermediate supports. Supports at equipment, change of direction, and every 20'-0" shall be per approved plans

Updated Bid Form (see attached)

An allowance fund of \$25,000.00 has been added to the project.

Signature_____

Date_____